

BUILDING REGULATIONS REGULARISATION REPORT

	Mr & Mrs Smith			Date:	1/7/19
Address: Tumbledown Cottage, Ebford Lane, Sidmouth. EX5 3RL				Weather:	Mild, no rain
Inspec	ted property address if different:			Inspector:	Jamie Wright
Works	to be inspected: Loft Conversion				
	Image of front of house for reference	General image of works to be inspected			
Key;					
1	Building regs compliant				
2	Minor buildings regs fail				
3	Significant fail				
4	Not able to inspect, but suspect fail				
5	Not able to inspect, further investigation require	red			
Inspe	ction;				
Work	s in line with Approved Document A	- structure			
	Element		Image attached	Estimated cost to rectify / investigate	Potential risk to life
3	Structural beams appear undersized		bol	£3,500	Medium
1	Floor joists adequate			£0	None
5	Rafter level insulation			£225	Low
Work	s in line with Approved Document B	 Fire warning and escape 			
3	Ground floor smoke detector not positioned co	prrectly		£250	Medium
3	Fire doors missing to first floor bedrooms			£1,250	High
3	First floor master bedroom window not suitabl	e for fire egress	bei	£450	High
1	First floor second bedroom window suitable fo	or fire egress			None
What	to do now?				
Option	1 : nothing				
	The works were completed more than 12 mon they can still apply to the courts for an injuncti infringments are of a significant enough nature compliance issues to be of a significant enoug minimal risk that legal action will be taken aga	on to prevent further use of the building if they e to be a risk to human life. We do not deem t in level for building control to apply for an inju	v deem the the the the the quality of	ouilding regulations works or non-	

Option 2: Obtain quotes for the full cost of repairs							
· ·	· · · · ·						
Option 3: Apply for regularisation from the local council							
Option 5. Apply for regularisation from the local council							