

BUILDING REGULATIONS REGULARISATION REPORT

Cilent:	Mr & Mrs Smith			Date:	1/7/19
Address: Tumbledown Cottage, Ebford Lane, Sidmouth. EX5 3RL			Weather:	Mild, no rain	
Inspected property address if different:			Inspector:	Jamie Wright	
Works to be inspected: Loft Conversion					

Image of front of house for reference



General image of works to be inspected



Key;

- Building regs compliant
- Minor buildings regs fail
- Significant fail
- Not able to inspect, but suspect fail
 - Not able to inspect, further investigation required

Inspection;

Works in line with Approved Document A - structure

	Element		Image attached	Estimated cost to rectify / investigate	Potential risk to life
3	Structural beams appear undersized		fei	£3,500	Medium
1	Floor joists adequate			£0	None
5	Rafter level insulation			£225	Low

Works in line with Approved Document B - Fire warning and escape

3	Ground floor smoke detector not positioned correctly		Eeil	£250	Medium
3	Fire doors missing to first floor bedrooms			£1,250	High
3	First floor master bedroom window not suitable for fire egress		f ei	£450	High
1	First floor second bedroom window suitable for fire egress				None

What to do now?

Option 1: nothing

The works were completed more than 12 months ago. Building control cannot enforce under a section 36 notice. However, they can still apply to the courts for an injunction to prevent further use of the building if they deem the building regulations infringments are of a significant enough nature to be a risk to human life. We do not deem the quality of works or noncompliance issues to be of a significant enough level for building control to apply for an injunction, therefore there is a minimal risk that legal action will be taken against you, or future property owners.